# U10/U20 USB Network Interface
QUICK START

1. Insert the CD into your CD-ROM drive

1. The OpenLDV™ installer starts automatically. If it doesn't, run **OpenLDV210.exe**.
2. Follow the on-screen instructions.
3. After completing installation, eject the CD.

> ⚠ You must have Administrative Privileges and Windows® XP, Windows 2000 or Windows Server 2003. Refer to the User's Guide on the CD for more information.

2. Connect the USB Network Interface to an available USB port

1. On Windows 2000 go to Step 3 "**Connect to LonWorks® channel**".
2. On Windows XP and Windows Server 2003, choose any of the three Windows Update options, at your preference. Click **Next** to continue.
3. Select "**Install the software automatically (Recommended).**" Click **Next** to continue.
4. A completion dialog appears. Click **Finish**.

3. Connect to LonWorks channel

- For the U10, connect the TP/FT-10 channel wiring to the detachable network connector.
- For the U20, plug the wall-plug coupling circuit/power supply into a power outlet, and connect the barrel connector into the U20's barrel jack.

4. Start your LonWorks software

1. Start your LonWorks software (LNS® applications including LonMaker®, OpenLDV applications, or LonScanner™ Protocol Analyzer).
2. Choose **LON1*** as the network interface.

   *Typically the USB network interface is accessed as **LON1**. If you have multiple network interfaces, start **LonWorks Interfaces** in Control Panel and then choose the **USB** tab.

Consult the User's Guide on the CD for more detailed information on these steps.